

LCD TELEVISION TECHNICAL BULLETIN

<u>MODELS</u>	LC26P70EK	LC26SD1EK	LC32BT8EK	LC32GD8EK
	LC32GD9EK	LC32P70EK	LC32RD1EK	LC32SD1EK
	LC37BT8EK	LC37GD8EK	LC37GD9EK	LC37GE1EK
	LC37P70EK	LC37RD1EK	LC37SD1EK	LC37XD1EK
	LC42RD1EK	LC42SD1EK	LC42XD1EK	LC46XD1EK
	LC52XD1EK			

SYMPTOM Program start and end time on the channel banner differs to EPG time.

CAUSE Software Issues.

ACTION Update DTV software to the latest version.

Sharp Electronics (UK) Limited

Reference – LV-218
Revision - 1

White – Carry out as required
Yellow – Carry out as required and whenever the unit comes in for service
Red – Carry out on all units